

Ghaleh Jalali Citadel

Kashan-Iran

Design with Nature
online seminar 2018

Mastaneh Mahfouzi

Challenges

Erosion

As there are no maintenance strategies about the structure of the walls, they are getting erosion gradually, which is harmful to both the walls and the surrounding nature.



Incompatible Functions



Incompatible Functions



Agriculture land

Improvement strategies

Awareness

As there is no enough awareness of the result of the neglections ,even in part so there is no future schedule for this site. The awareness can start in educational part and in part




Awareness




Awareness

Omit the Incompatible functions



Incompatible functions




Erosion

Renovating the walls

Renovating a part of walls



Initiating new functions



As there is lack of public spaces and greenery making a local park can be a strategy for GHaleh Jalali citadel.



Current park close to the citadel